


CORNER RECORDDocument Number CR 6997City of OaklandCounty of Alameda, CaliforniaBrief Legal Description City of Oakland Street Monument**CORNER TYPE**Government Corner
Meander
Rancho☐
☐
☐Control
Property
Other☐
☐
☒**COORDINATES (Optional)**

N. _____

E. _____

Zone _____ NAD27 ☐ NAD83 ☐

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 ☐ NAVD88 ☐Meas. Units: Metric ☐ Imperial ☐Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner record is being filed to
ESTABLISH the position of an existing monument PRIOR to street or highway construction.

A description of the physical condition of the monument as found and as set or reset:

See sketch on back.**SURVEYOR'S STATEMENT**This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyor's Act on March 17, 2015Signed [Signature]P.L.S. or R.C.E. No. LS 8971**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received _____
and examined and filed _____3-20-15
6-8-15Signed [Signature]P.L.S. or R.C.E. No. 5726Title COUNTY SURVEYOR

County Surveyor's Comment: _____

