


# RECORD OF SURVEY

PORTION OF SECTION 6, T.1N., R.15E., M.D.M. &  
PORTIONS OF SECTIONS 21, 28 & 32, T.8N., R.15E., M.D.M.  
AMADOR COUNTY CALIFORNIA  
GENNIS & ASSOCIATES ENGINEERS  
SACRAMENTO, CALIFORNIA

Prepared for:  
U.S. Department of Agriculture - Forest Service  
El Dorado National Forest  
Panther Ridge Cadastral Survey  
R5-78-105




**SURVEYOR'S CERTIFICATE**  
This map correctly represents a survey made by me or under my direction in conformance with the requirements of the Land Surveyor's Act at the request of the U.S. Forest Service in July 1979.

*Alan Richter*  
Alan Richter LS3383

**BASIS OF BEARINGS**  
The basis of bearings shown hereon is true north determined by the mean of solar observations made near the S 1/4 of Section 21 and the E 1/4 of Section 32 shown hereon.

- LEGEND**
- Found standard BLM brass cap monument set in 2 1/2" I.P.
  - Set 2" C.I.P. stamped LS3383, 1978 or 1979 and appropriate designation.
  - + Computed point - nothing set.
  - ① Key to bearing tree description on Sheet 3 of 3
  - Approximate location of existing main road.

**COUNTY SURVEYOR'S CERTIFICATE**  
This map has been examined for conformance with the requirements of the Land Surveyor's Act this 2 day of August, 1979.



*John Carstensen*  
John Carstensen RCE22323  
County Surveyor

**COUNTY RECORDER'S CERTIFICATE**  
Filed this 22nd day of August, 1979 in Book 32 of Record of Surveys at Page 30 at the request of the Amador County Surveyor.

*Sheldon D. Johnson*  
Sheldon Johnson  
Amador County Recorder  
By: *Marlene Cretz*  
Deputy

